



<p>①</p> <p>Ø18 L = 955</p> <p>=11</p>	<p>②</p> <p>M8x30</p> <p>=11</p>	<p>③</p> <p>=13</p>	<p>④</p> <p>=11</p>	<p>⑤</p> <p>Ø18</p> <p>=1</p>	<p>⑥</p> <p>Ø10-50</p> <p>=4</p>	<p>⑦</p> <p>=2</p>	<p>⑧</p> <p>Ø6-90</p> <p>=2</p>	<p>⑨</p> <p>PZ3</p> <p>=4</p>
<p>⑩</p> <p>=1</p>	<p>⑪</p> <p>Ø4.8-13</p> <p>=8</p>	<p>⑫</p> <p>Ø12-60</p> <p>=1</p>	<p>⑬</p> <p>=1</p>	<p>⑭</p> <p>Ø8-80</p> <p>=1</p>	<p>⑮</p> <p>=2</p>	<p>⑯</p> <p>=1</p>	<p>⑰</p> <p>=1</p>	<p>⑱</p> <p>Ø6-60</p> <p>=2</p>
<p>⑲</p> <p>Ø50-1400</p> <p>=1</p>	<p>⑳</p> <p>=2</p>	<p>㉑</p> <p>Ø3.5-25</p> <p>=22</p>						